_	Weather Consent Decree Water Testing Form	Page 1 of 1		
Sewershed: Gwynns Falls	Company: Savin	Date: <u>7/6/2009</u>		
Test to be performed:  Smoke Dyed Water X	Ground Condition:  Dry ✓ Damp ☐ Wet ☐	Supervisor: JAW		
Manhole_ID: S05MM1003MH	Test ID: <u>D1032-034028</u>	Notification Made: NA (Residents, Fire, 311)		

Field Sketch: Show all manholes with Numbers, Blower Placement Locations, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photo Numbers.



Defect Loc	Obs_ClockFrom	Obs_ClockTo	Observation	Obs_Remarks
0			Start of Survey	
0			Manhole	S05MM1003MH
0			Water Level	
131			Dye Test Not Visible	@ TF - downspout
139.1000061			Dye Test Not Visible	@ TF - downspout
169.8000031			Dye Test Not Visible	@ TF
169.8000031			End of Survey	DYE TEST COMPLETED